



高压内螺纹转中压外螺纹

Female High Pressure to Male Medium Pressure

P 高压接头	Px 中压接头	产品编号 Product No.	尺寸数据 in.(mm)			工作压力 Psig(bar)
			L	D	F (六角)	
1/4	1/4	-HFM-H04-M04	1.37 (34.9)	0.09 (2.3)	0.75 (19.1)	20000 (1379)
1/4	3/8	-HFM-H04-M06	1.50 (38.1)	0.09 (2.3)	0.75 (19.1)	20000 (1379)
1/4	9/16	-HFM-H04-M09	1.69 (42.9)	0.09 (2.3)	0.94 (23.8)	20000 (1379)
1/4	3/4	-HFM-H04-M12	1.75 (44.5)	0.09 (2.3)	1.19 (30.2)	20000 (1379)
1/4	1	-HFM-H04-M16	2.37 (60.3)	0.09 (2.3)	1.50 (38.1)	20000 (1379)
3/8	1/4	-HFM-H06-M04	1.67 (42.3)	0.11 (2.8)	1.00 (25.4)	20000 (1379)
3/8	3/8	-HFM-H06-M06	1.81 (46.0)	0.13 (3.2)	1.00 (25.4)	20000 (1379)
3/8	9/16	-HFM-H06-M09	1.94 (49.2)	0.13 (3.2)	1.00 (25.4)	20000 (1379)
3/8	3/4	-HFM-H06-M12	2.13 (54.0)	0.13 (3.2)	1.19 (30.2)	20000 (1379)
3/8	1	-HFM-H06-M16	2.50 (63.5)	0.13 (3.2)	1.50 (38.1)	20000 (1379)
9/16	1/4	-HFM-H09-M04	1.87 (47.6)	0.11 (2.8)	1.38 (34.9)	20000 (1379)
9/16	3/8	-HFM-H09-M06	2.00 (50.8)	0.19 (4.8)	1.38 (34.9)	20000 (1379)
9/16	9/16	-HFM-H09-M09	2.19 (55.6)	0.19 (4.8)	1.38 (34.9)	20000 (1379)
9/16	3/4	-HFM-H09-M12	2.37 (60.3)	0.19 (4.8)	1.38 (34.9)	20000 (1379)
9/16	1	-HFM-H09-M16	2.81 (71.4)	0.19 (4.8)	1.50 (38.1)	20000 (1379)