



高压内螺纹转高压外螺纹
Female High Pressure to Male High Pressure

P 高压接头	Px 高压接头	产品编号 Product No.	尺寸数据 in.(mm)			工作压力 Psig(bar)
			L	D	F (六角)	
1/4	1/4	-HFM-H04-H04	1.44 (36.5)	0.09 (2.3)	0.75 (19.1)	60000 (4137)
1/4	3/8	-HFM-H04-H06	1.69 (42.9)	0.09 (2.3)	0.81 (20.6)	60000 (4137)
1/4	9/16	-HFM-H04-H09	1.75 (44.5)	0.09 (2.3)	1.19 (30.2)	60000 (4137)
3/8	1/4	-HFM-H06-H04	1.75 (44.5)	0.09 (2.3)	1.00 (25.4)	60000 (4137)
3/8	3/8	-HFM-H06-H06	2.00 (50.8)	0.13 (3.2)	1.00 (25.4)	60000 (4137)
3/8	9/16	-HFM-H06-H09	2.13 (54.0)	0.13 (3.2)	1.19 (30.2)	60000 (4137)
9/16	1/4	-HFM-H09-H04	2.06 (52.4)	0.09 (2.3)	1.38 (34.9)	60000 (4137)
9/16	3/8	-HFM-H09-H06	2.37 (60.3)	0.13 (3.2)	1.38 (34.9)	60000 (4137)
9/16	9/16	-HFM-H09-H09	2.50 (63.5)	0.19 (4.8)	1.38 (34.9)	60000 (4137)